600 sec for the te	2204.623 Lbs	ton metric=	*	Kilo ·	: ni thgiə
·		•			

0.50% Purity and Efficiency tolerance

2.00% Input feed variation tolerance

													ja Are															
	%00	00 001 9	%00 00 L	%00 00 L	%00'001	%04'94	%19'88	%00'001	%00'001	%00 00L	%46 66	%89'29	%69.88	%87 ES	%£1.68	%11'89	%9L'9L	%68.56	%21 86	%L0:06	%80'26	%00 00 L	%/9°E6	%17.86	%98'46	%02.66	%02.66	(youəioili)
· . · ·	%0€	96.35	%00'00L	%00 00 L	%00 00 L	%1 V 18%	%18.66	%00 004	%00:00£	%46.88	%/916	%60'86	%0£66	%86°96	23.55%	%97,60	%E0.74	96 50%	%68.96	97.22%	%99.26	%00'96	%09'96	%8¥ 06	%97-66	%67/86	%99/76	Vinuq lenateM
			%h210		3.56%		%99'01	4	%9Y.01		%¥0.66		8410%		5.57%		%09 0		%E8:E		5.07%		%80'7E		%881.		%16'9	epage beat fugni
11/11 11/11	30.00 - 30 CO.00 CO.	1.0.	0:0	Þ'0	4.0	0,1	l'I	1.2	1.2	9.4	0.4	1.9	2.2	4.0	₽'0	0.0	1:0	1/0	Þ :0	2.0	2.0	1'0	1.0	5.0	2.0	Ζ'0	L'0 '	TuoH\enoT
121.97 235.96	SHALL SHALLSAN	98.3	0	0	0	21,6	1.2.1	0	0	191,63	69:99	22.38	1,13	99.56	78.AE	248	2.48	3.14	2.24	90.E	90'8	18.0	68,81	81.0	81.0	68.r	S:38	Contaminents
EP.2381 EP.238	ational post vegasiv	9Z'6	4,42	66:99	66'99	9:1/1	70.481	199.35	199.35	64.647	86.788	324.07	37.472	Z0169	75.47	8.2	99'6	94.29	Z6.17	33,12	97.76	20,25	68.81	49.16	76.26	74,011	96'011	Bunker Weight
वंचेड वंचेड		35'5	4.42	, 0	0	0	. 0	0	0	Ó	0 .	0 .	0	0	0	0	0	0	0	0	0	0.	0	0	0	0	0	- Rejected
66'99 66'99		0	0	66'99	66'99	0	0	0	0	0	0	0	0	0	. 0	' 0	0	. 0	0	0	0	0	0	0	0	0	0	ho2_919
99,361 98,861	\$50 X4 50 00000	0	0	0	0	091	182,86	0	0	87,72	12.7	87.71	0	0	0	0	0	0	0	0	0	0	0	0	0	0	. 0 .	Cardboard
199,32 199,32		0	0	. 0	0	0	0	SE.991	199,32	0	0	0	0	. 0	0	0	0	0	0	0	0	0	0	0	0	0	0	News Glass
446,42 446,42 446,42 446,42	ook at	0	0	0	0	67'9L	0	0	0	96,119	89,66 67,118	0 69°408	69.676	91.59	65.18	0	0	95,1 0	0 1:28	0	0	0	n	0	0	0		Mixed_Paper
07.74 07.74 07.74 07.74	THE EAST OF THE	o O	a a	0	0	11.9	121	. n	0	8.24	88.29	97	96'0	.59°51	Z9'68	0	0	1.28	89.0	. Z9'0	Z9'0	18.0	1 90	81.0	81.0	6.1	E.1	enpiseA .
9.21 9.21	1000	0	. 0	0	l n	0	1 0	0	0	0	1 0	0	900	1.35	1 0	27.3	20'Z	0	0 0	29.0	23.0	1 F8 U	N90	OF U	0 0	0	0	sbisduT
86.07 86.07	- 6	38.6	n	0	n	n	0	0	0	0	10	n	n	ZG't	0.21	0	0	26.28	89.69	2.0	2.0	n	n	,	0	0	67:0	13d
38.29 38.29	A	7 1 7 L	0	0	0	0	0	0	0	0	0	. 0 :	0	98'6	99'0	2.48	2,48	0	0	30.08	7.48	0	0	0	0 -	95.0	917:0	HDBE
44.91 44.91		0	0	0	Ó	0	0	D D	0	. 0	0	0	0	- 0	1.25	0	0	0	0	0	0	19,44	61,81	0	0	0	0	elleq mont negaq_b
89.66 89.66	1	0	0	0	0	0	0	0	0	SÞ:0	24.0	0	0	1.32	62'0	0	0	6.0	0	90'0	9070	0	0 -	91,16	92.26	81.0	61.0	muinimulA
34.601 34.601	j.	0	0	0	0	0	0	0	0	0	0	0	0	88.0	88,0	∴ 0	0 .	0	0	0	0	0	0	Ó	0	108'28	86,801	иjT
Total System Total Machin		Machin	System	Machir	System	Machin	System	Machine	System	Machin	System	Machir	System	Machir	System	Machir	System	Machin	System	Machir	System	Machine	Systen	Machir	System	Machir	System	Wateria
<u> </u>		pəşəəl ğ	- leਸ਼	nos	91 <u>9</u>	Daso.	db1s2		· (원명	- 6 S∧	v o M	Paper	bəxiM	ิ ซี อิท	Resid	. Ebi⊿ . g	sqnT	e	<u> </u>) 33	IGH .	<u>ouejj</u>	Hixed Feel Feel Feel Feel Feel Feel Feel Fe	muin g	imulA 	ī ū	II	\$010-05-0 1

$\mathcal{Z}_{i,j} = \mathcal{Z}_{i,j} = \mathcal{Z}_{i,j}$	-		 13-	·/	7
			20		B
		ठ	7	7	7
					1 1

әбел	Beauri	Serge	
	элебэ	eny Le	

Machinex Tech:

Machinex ingeneer:

Bluewater Recycling Association

Single Stream MRF/Automated Collection Project

Submitted by: Francis Veilleux, President

1.0 Table of Contents

2.0 Introduction
3.0 MRF Construction and Monitoring
3.1 Project Schedule4
4.0 MRF Operations6
4.1 Labour Requirements6
Processing Costs
4.3 Problem Areas
4.3.1 Large OCC
4.3.2 Paper Labels and Small Paper
4.3.3 Film in Paper with AB21
4.3.4 S12 Transition 8
S4 Disk Spacing
4.3.7 Film Recovery
4.3.8 OCC QC Position
4.3.9 Fines Magnet
4.3.10 Baler Efficiency
4.3.11 Air Emissions
4.3.12 Plastic Quality Control Conveyor Speed1
4.3.13 Large Paper Handling on Glass Cleanup System1
4.3.14 Static Electricity Nuissance16
4.4 Efficiency and Effectiveness of System1
4.4.1 Plastic Quality Control Secondary Pass Performance11
4.5 Maintenance Requirements12
4.5.1 Separator Angle Sensor12
4.5.2 Shaft on Accelerator Conveyor1
4.5.3 Optical System Alignment13
5
Failure
ts
gramming
4.8 Production Capacity1
5.0 Curbside Collection Monitoring15
.2 Curbside Impact
.3 Health and Safety Issues
.4 Customer Feedback
6.0 lessons learned
7.0 Appendix A

2.0 Introduction

collection system involving the use of automated collection vehicles and wheelie bins instead of the traditional blue box with a manual collection system. a new single stream processing facility to facility the Association's conversion to a Agreement #135, this report provides certain information pertaining to the installation of In accordance with the requirements of the Continuous Improvement Fund Project

This report is divided into three sections:

- MRF Construction and Monitoring MRF Operations
- **Curbside Collection Monitoring**

This is the final report of four amalgamated quarterly reports.

3.0 MRF Construction and Monitoring

3.1 Project Schedule

December 2, 2009	December 1, 2009	Start up
December 1, 2009	Oct 12-Nov. 30, 2009	Installation of New Equipment
October 8, 2009	October 1-11, 2009	Removal of Existing Equipment
Completion	Scheduled	Task

cooperation of the weather and the availability of the right trades persons. The Association completed the removal of existing equipment ahead of schedule with the

to facilitate the new installation. An unplanned electrical service upgrade was completed during the equipment installation

operating efficiency. adjustments in chutes, platforms, and railings that were deemed preferable for long term budget as promised. but once everything was rolling Machinex Industries delivered the facility on time and on The installation was slow at first with some of the equipment being delayed at the factory We delayed the completion by 24 hours to make various minor

completed successfully on the first try. commissioning. that our staff needed to get over the holiday rush and learn the system better before While the final commissioning was originally scheduled for January, we jointly agreed As a result it was moved to the week of February 1, 2010 and it was

3.2 Project Budget

		Difference
\$4,433,326	\$4,340,030	Total
107,640	107,640	Freight & Commissioning
875,290	875,290	Installation
210,755	210,755	Glass Cleanup System
96,085	96,085	Container Storage
816,680	816,680	Container Sorting System
60,375	60,375	Fiber Storage
359,415	359,415	Mix Paper Optical System
46,040	46,040	Pre-sort Residue Compactor
312,000	312,000	Screens
380,495	380,495	Structural Steel
732,755	732,755	Mechanical Equipment
32,574	100,000	Miscellaneous
212,560	40,000	Electrical Provision
74,095	72,500	Receiving Modification
53,921	60,000	Concrete Work
\$62,646	\$70,000	Equipment Removal
Actual	Budget	Item

The Machinex installation was delivered on time and on budget.

The Association did have some unexpected electrical services upgrades to complete for the project to proceed. These new services added \$180,000 to the project costs which were the sole contributor to an overall extra expenditure over budget of \$93,296.

4.0 WRF Operations

4.1 Labour Requirements

three months we studied the productivity of each position and assessed the quality of the to optimize quality and throughput. outgoing materials to find the right number of sorters at the right locations in the process During the initial start up we used 15 sorters supported by 4 operators. During the first

not anticipate making any significant changes to this allocation until we have enough materials to fill a complete shift. We are currently operating with 12 material handlers and 4 equipment operators. We do

original eight hours in the winter and 10 hours in the summer. typically run out of materials after approximately 6 hours of production time in lieu of the are currently running with approximately the same number of staff as before but we The Association anticipated labour costs savings of up to 50% with the new system.

also additional baling that needs to be done. duties around the facility or assist with odd jobs that occur from time to time. leave, the remaining employees are used to sort e-waste, perform general housekeeping afternoon to guarantee some base income. In order to keep the existing staff we have made it optional for anyone to leave in the Approximately half the employees usually

4.2 Processing Costs

quarter of 2009 is compared with the second quarter of 2010. In order to provide some financial performance for comparison purposes, the second

Total Processing Costs	Building Repairs & Maintenance	Utilities	Supplies(including bale wire)	Disposal	Equipment Repair & Maintenance	Wages	Item
271,326	34,225	12,826	44,864	11,215	12,175	156,021	2009
447,065	36,598	26,742	42,370	10,487	151,067	174,801	2010

to school in September and a driver who was in the plant on modified work as part of his return to work plan. Otherwise we ran with 12 sorters, same as 2009. Hours were previously discussed under MRF Operations. Wages are higher in 2010 due to the addition of an apprentice millwright who will return

of \$118,000 for the new equipment. Equipment repairs in 2010 include a one time purchase of essential parts from Machinex

the program, residue rates have steadily fallen below 4%. Since the recovery of plastic film has resumed and the addition of mixed rigid plastic to Residue rates for the 2nd quarter were 5.27%, virtually unchanged from 2009 at 5.32%.

that the new equipment requires. Through CIF funding we will be conducting an energy We have seen a large increase in our hydro costs due mostly to the increase in demand audit to see where we can improve.

4.3 Problem Areas

needed. Here is a sample of some areas we have had to deal with are sometimes positives and other times problematic where system adjustments are Like any new process implemented, a variety of side effects manifests themselves which

4.3.1 Large OCC

the materials to spread evenly onto the presort conveyor initially caused some issues with Because of the 90 degree turn at the beginning of the system, the transition that allows staff to give the boxes a tug when needed to allow them to flow freely. transition and block the incoming flow. A simple tool has been developed for the presort excessively large cardboard boxes such as "Gaylord" boxes which would rest on the

4.3.2 Paper Labels and Small Paper

removing paper contaminants but the exercise really comes down to the best compromise between size recovered and excessive contamination. We are currently evaluating adjusted to ignore paper labels found on water bottles, detergent bottles, etc so are the smaller pieces of paper resulting in unwanted residue. The machine can be effective in the paper is removed along with any containers with a "paper" label. As the target size is the size of the piece of paper you wish to eject. If the smallest size is selected, most of well as any mixed paper that is with the containers. The optical sorter does not know or care about the source of paper. You can simply program it to identify and eject paper and As part of the "container" processing area we use an optical machine to sort containers options to possibly utilize our second optical sorter in the cleanup task.

4.3.3 Film in Paper with AB21

along with any paper that may have been overlapping at the time of ejection. For that reason, we designed a vaccum system to recover the fibres that are erroneously ejected. As part of our mixed fibre cleaning system we use an optical machine to remove non optical system from removing PE resins and let our quality control person handle those mixed fibre storage bunker. After some system process reviews we opted to stop the the ejected plastic bags also that were missed on presort and returning them to the clean paper contaminants. The system is very effective at recovering the lost fibres unfortunately it was recovering The system is effective in removing the majority of contaminants

4.3.4 S12 Transition

result has been a build up of materials on the ledge that eventually gets dragged in with The transition at the end of the finishing screen is tapered for unknown reason. regular basis until the transition can be modified to eliminate the issue. belong there. larger than two inches, some paper was found in the glass system residue that did not the fines that fell through the screen. Since our fines cleaning system rejects anything As part of our operating procedure, we now clean the ledge area on a

4.3.5 S4 Spill

containers resulting in the ejection of some containers over the side of the unit. The top of the separator will be covered in mesh to prevent any further spillage. We have observed the cardboard separator to be very aggressive from time to time on all

4.3.6 S4 Disk Spacing

without any quality issues after the quality control position. spacing, we have found the vast majority of all cardboard is removed by the screen cardboard escaped the cardboard separator screen. Just as the largest cardboard caused some issues with the feed system, the smallest After an adjustment to the disk

4.3.7 Film Recovery

Until recently, we simply disposed of the film with any contaminant removed at the that the quality of the film in a single stream system would be acceptable to end markets. Our new system design purposely left plastic film with different options since the material was in decline with all the new fees in grocery stores and we were not convinced presort area.

are deposited in one of two 6 yard front end containers that are replaced once per day. of production in the compactor before being brought in to be baled. damaging contaminant at the presort. The change allows to store film for up to 50 hours We now use the compactor at the presort to hold the film recovered and only remove The contaminants

4.3.8 OCC QC Position

plastic containers and some newspaper that must be returned to the processing line but the OCC QC position since we reduced the disk spacing. We are now getting more large the chute was too narrow resulting in some unnecessary plugging. We have had to increase the size of the chute for materials being returned on the line by

4.3.9 Fines Magnet

receiving side of the magnet forcing the material to hit the belt in the center instead of the side of the permanent magnet affecting the belt tracking. ferrous lids from the fines. However, some of those lids have been accumulating on the The overhead magnet on the fines processing line has been very effective in removing We have since raised the

4.3.10 Baler Efficiency

materials. Building limitations also limited the width of the belt feeding it to 48 inches. The Association utilizes a 10 year old Ambaco 7243 horizontal baler to bale all of its

that fluffers would no longer be needed for normal operation greatly improving the system. It was hoped that the new single stream system would agitate the paper enough efficiency of the baler. The baler was not replaced as part of the upgrade to test its efficiency with the new

The baler is capable of adequately baling paper without fluffers however bale weights are reduced by approximately 20%. This is not critical for paper as paper shipments are result, we are required to use the fluffers to maintain our pressure which greatly reduces affecting the density of other materials such as plastic and metal in a negative way. usually overweight and they never cube out. the efficiency of the baler. However, the reduced bale weight is

alternate between paper and plastic or metal after every two bales to maintain our pressure losing and productive advantage a single ram baler of this design can offer us. With the speed of the new system and the limited storage capacity, we are required to

material baled are those baling against a solid surface like a closed ram baler or a two only a few machines can handle our throughput potential. throughput limitations. Two ram balers are generally slower that a single ram baler and ram baler. The only baler types capable of baling any material without worries about the last Closed ram balers are not suitable for operations our size because of

new baler employs unique technologies making it capable of twice the throughput of the the Harris Grizzly EHD baler is expected to take place in the first quarter of 2011. The current baler without the need for any fluffers. A new two ram baler has been ordered to manage our mix of materials. Installation of

4.3.11 Air Emissions

heated, there is no mechanical ventilation. buildings like ours, it is a compromise you have to live with. Because the building is the whole process line. The receiving area shares a common areas with the processing larger telehandler to stack incoming materials higher and reach the drum feeder that feed As part of the new MRF design, the Association replaced its skid steer equipment with a In new constructions, it is common practice to separate the two, but in existing

matter (DPM) emissions resulting in less than ideal air quality. Air emission standards One of the unexpected results of the equipment change was the rise in diesel particulate As a result, we routinely perform air quality tests to ensure the safety of our employees. were surpassed and employees were required to wear masks.

plan B with 100% biodiesel which is readily available and sustainable in our indoor converter on the telehandler. The results were better, but not good enough. Our immediate reaction was to replace the current coloured diesel fuel to the Ultra Low Sulphur Diesel used in our trucks. We tuned up the equipment and installed a catalytic summarized below. heated environment. The results were clear and noticeable. Problem solved. All data We moved to

6-15 ug/m3	32-119 ug/m3	B100 Biodiesel Approach
115-346 ug/m3	234-519 ug/m3	Low Sulphur Diesel Approach
253-503 ug/m3	202-715 ug/m3	Initial Reading
308 ug/m3	160 ug/m3	Standard to be met
DPM as Elemental Carbon	DPM as Total Carbon	Item

4.3.12 Plastic Quality Control Conveyor Speed

distribute the materials to maximize the efficiency of the optical secondary quality fed in a batch process. as they flow differently on the conveyor. Machinex, a second adjustment is now possible to differentiate between PET and HDPE the sort. Only one adjustment was available on the system initially. With the help of control pass while providing an even flow for the material handler to effectively finish The Association uses one conveyor to perform quality control on PET and HDPE that are Three conveyors operated on time delay are used to evenly

4.3.13 Large Paper Handling on Glass Cleanup System

month, we are now reprocessing this material successfully rather than shipping it to landfill. The recovery is very high if the loader operator blends it properly with fresh because of overflows from other sources. Despite the low generation, 30 cubic yards per they went through the screens, other times they are larger and were found in the mix the end of the line. The pieces of paper are sometimes long and skinny explaining why quantities. This material makes up the majority of the material found in the compactor at have found that some paper larger than 2" is often found in the glass system in small The glass cleanup system was designed to handle all materials of a 2" minus nature. We

4.3.14 Static Electricity Nuissance

the stored energy to be released through their body on to the steel platform that is charge was not released until our material handlers were handling the bags allowing for susceptible to building an electrical charge as they rub together. That static electrical system improving material separation. in the air. We discovered the source of the problem was the drum feeder unit. The drum employees in the presort area. Those varied based on the time of the year and humidity Since the new system was installed, complaints of static electricity shocks were filed by simply transferred the problem to other body parts such as their belly that made contact grounded and the rubber belt was not. While rubber mats and anti static boots helped, it feeder rotates and holds excess materials back to provide an even constant feed in the reaching the material handlers. presort area to dissipate the stored energy in the bags through the equipment before with various metal components. The solution was a chain curtain installed prior to the Some materials like plastic bags are more

4.4 Efficiency and Effectiveness of System

efficiency and effectiveness compared with the equipment efficiency and effectiveness for each commodity managed by the Association. meeting all of the current market demands. Appendix A outlines the details of the system The Association has been operating the facility at approximately 12 tonnes per hour

4.4.1 Plastic Quality Control Secondary Pass Performance

results of this approach. being a secondary batch process quality control pass. separator in North One of the unique characteristics of this facility is the utilization of the largest optical America to perform multiple functions. In this report, we publish the The most unique function

roughly 800 mm each. nine separations. two ejection valves capable of ejecting up and down with rejects in the middle for up to Our 2800mm wide optical separator is separated in three channels, each equipped with The channels are distributed into one roughly 1200 mm and two

HDPE bottles while the less efficient downward ejection is used to remove paper from removal prior to returning to the optical sorter. The centre channel is the first channel used. Its higher quality upward ejection is used for The remaining materials are sent to an eddy current for aluminum

missed materials. be residue but not before being inspected by a quality control station to recover any while plastic containers are downward ejected. The second channel located on the left side is used to eject upward the PET containers The remaining materials are deemed to

only the upward ejection is used to remove contamination since in theory all materials improve their quality before being conveyed to a quality control station. In this channel, achieve a 99.75% purity level with a second pass. machine can achieve a 95% purity level on the first pass, in theory it should be able to presented are acceptable. The third channel located on the right side is used to batch process the PET and HDPE to The thought process behind this arrangement was that if the

Efficienc	Purity	18.0%
	Ħ	
Z.	Ħ.	20.0
₩.	×	165.00
ĽΨ		
- 5		
		, u.s.,
	6124504653	HDPI
		0.5
		100
		F 49 7 80
\O	VO.	4
95.4%	94.6%	First Pass
		1
78	- 20	ਾਹ
~	_ ∂ \	
	BASEWSE.	
		14
		2
ဟ	ဖ	6
94.4%	96.9%	Second Pass
4	vo .	<u>o.</u>
120	20	in es
	52-02-0-02-0	SS.
		10
V		
	5:55:55	
		100
	BM2903W	
NO.	S	(C)
90.0%	96.9%	
	· 6	0
(6)	্ত	(1)
•	o>	
		- 92
		16
	1511537258	
Professional and Committee	""	CONCESSA INCOMESSA IN

Efficienc	W.O.	Purity	200
	Mã.	C	
	(4)		10000
	18		
	W.	- 7	
	m		
	24		
	100		
	23		- 0
(a a a a a			7.0
	1992		PET
	,		658
	12		
	8		
	M		
	133		
	13		
	W.		100000
	320		
	M		
	W.		
	8		
	88		
	2		
	88		
	3.2		
			3/2/40
	UO		
	奫		First Pass
95.4%	3	95.2%	
	mã		
	쬻	•	400
N		N Y	
			999
			
9	%	9	
	繎		
	×		
	No.		
	V2		
	282		
	32%		
	84	8/52468)	2-88-8/A
	×		
	*		
	m		
	9%		
	₩.		
	*		
	14	20.5F15.2Y.	
NO.	***	VA.	
	8		(5)
///	W		- A
97.4%	%	96.2%	
	8	×	90.00
	×	•	
	88		econd Pas
	W		
	m		
100	*		-/////
	103		1999
	4		
	30		
	28		44.5
	icili.		
	12		
	#		() () () () () () () () () ()
	1		
	8		F 4 - 6
	92		1000
	*		
	œ.		200
	*		47-0
92.9%	25	96.2%	Overa
- 3.5		~~	
KAN NEE	íğ.		
NO.	2	N.	
		\$5	7.60
	115	\sim	
	1		and the second
	₩.		
	ŶŔ		
	1		
	88		
	1		540,340
	:10	and children	Service Control

2-5%. The result is the possibility to improve the purity by 1-2% but at the loss of efficiency of

4.5 Maintenance Requirements

equipment. and a separate shift will be required to completed the necessary work to maintain the afternoon when we run out of material. As the system ages, more time will be needed part of our operations. At this time we are primarily performing maintenance during the Normal preventative maintenance has been performed on the equipment since the start It consists of a multitude of daily, weekly and monthly tasks that are scheduled as

that caused some alarms on one of the compactors. Both compactors were upgraded to a Since then, we have not had to align the machine. per week. It was traced to a defective communications card that was replaced in January. We initially had some issue with our wide optical system getting out of alignment once larger breaker. We also had a week circuit breaker

4.5.1 Separator Angle Sensor

monitored instead of allowing the PLC to make automatic adjustment. Material quality cause any downtime but it did reduce our abilities to a manual adjustment that had to be sensitive that they were reading the angle fluctuations from the vibration of the machine. would have suffered during that period but to no measurable degree. The new equipment came equipped with new angle sensors that turned out to be so We had to abandon the design and return to the original equipment. The issue did not

4.5.2 Shaft on Accelerator Conveyor

that was suspected to be a material build up on the supporting rollers at first until the tail pulley actually broke in half. feeding the container optical system. We experienced head and tail shaft failures on the 2.8m wide accelerator conveyor The failure introduced itself as a vibration at first

automatic tracking system and there were no written procedures to properly replace the shaft. We were successful in fabricating special tools and develop appropriate exact cause of the failure is still under investigation. procedures to extract the broken shaft and install the replacement shaft in 15 hours. The The location of this pulley was very difficult to reach, it also was attached to an air driven appropriate

re-occurrence in the future. before it completely broke. The head pulley on the same conveyor experienced the same problem but we replaced it Both pulley have been redesigned by Machinex to prevent

4.5.3 Optical System Alignment

the temperature. Since our facility is heated, the temperature changes are not as extreme connection. The alignment process is not onerous for us as it can be done remotely through our online but we did require a new alignment in late spring when the summer heat was constant. The optical systems have been performing well but we noticed that they are affected by

4.5.4 Conveyor Tail Pulley Failure

bearing was installed backwards which prevented the introduction of grease. container crusher. A bearing failure resulted in a worn shaft that had to be replaced. The During the third quarter, we had to replace a tail pulley on a narrow conveyor below our

4.5.5 Optical System Purge Valve Failure

cause of the problem. A simple cleaning of the valve resolved the issue Each of our optical systems had the purge valve stick open at some point. In each instance small particles of aluminum from the air lines installation were found to be the

4.6 Health and Safety

to the implementations of this processing system since its implementation. and reduce WSIB claims. One of the goals of the project was to provide a safer work environment for employees The Association has not recorded any lost time injury related

4.7 Commodity Markets

result of an experiment where we ran the system in excess of 18 tonnes per hour with 14 newspaper sold as #8 News that were downgraded to #6 News. system since its implementation. The Association had two downgrades related to the implementations of this processing The two downgrades were on two consecutive loads of The two loads were the

visited our facility and they were happy with the quality produced. Otherwise, we have had no market issues. Buyers for paper, plastic, and glass have

The Association has had no downgrades or rejections since the first quarter

with our mixed paper. The value is substantially greater at \$249 per tonne in lieu of \$27 per tonne for mixed paper. We have started to sell our shredded paper as a separate commodity instead of mixing it

marketing issues. We have also resumed our separation of plastic film as outlined above without any

4.7.1 Wixed Plastic Programming

only. proportionately. plastic containers in lieu of the #2, 4, and 5 that had been programmed for tubs and lids As of October 1, we reprogrammed our container optical system to separate all mixed The plastic recovery has increased noticeably, while the residue decreased

4.8 Production Capacity

tonnes per hour. capacity by 44% while reducing costs per tonne as a result of economies of scale. The The Association estimated the new facility would be capable of increasing the production facility capable of handling 48,000 tonnes per year or 100% more than the old facility. productivity test performed thus far indicate the system is capable of processing up to 15 Based on a two shift operation 5 days per week this translates into a

from single stream collection but do not have the processing capacity to do so. readily handle more tonnes to process in the system. As a result, the Association is willing and able to assist other programs wishing to benefit We can

5.0 Curbside Collection Monitoring

5.1 Labour and Equipment Costs

system requires a mere 14.5 hours per week collecting 17% more materials. the manual collection system required 31 hours per week, the automated collection has maintained its effectiveness and efficiency as documented in earlier reports. The automated collection system has been in place in St. Marys since October 2008. It

34.3% less than the traditional manual top loader system. capacity the carts give the residents, the automated system results in a net cost that is only requires biweekly collection in lieu of weekly collection as a result of the additional because the automated collection vehicle is so much faster per stop, has compaction, and 40.4% more per hour than a traditional manual top loader collection vehicle. However, The cost to operate and maintain an automated vehicle including the cost of the carts is

One container had to be replaced because of vandalism.

5.2 Curbside Impact

The capture rate is 17% higher than the traditional blue box system

place in June. Goderich while another 953 were distributed in Seaforth. Their first collections took benefiting from this program. those communities. The Town of Goderich and the Ward of Seaforth were the next areas Other communities have embraced the concept and we have begun the expansion into The Association has distributed 3,026 wheelie bins in

collection program. Approximately 4,000 containers were distributed during the first two weeks of November. The Municipality of Central Huron is the latest to be converted to the automated

The Association has not experienced any collection equipment failure to date

5.3 Health and Safety Issues

the implementations of this collection system since its implementation. and reduce WSIB claims. The Association has not experienced any lost time related to One of the goals of the project was to provide a safer work environment for employees

5.4 Customer Feedback

and businesses wishing to recycle more. The residents of St. Marys continue to accept the new program and embrace its Twelve more containers were delivered in the last quarter to households

now feel like second class citizens. They want the wheeling bins Seaforth questioning their council why they did not receive the new wheelie bins as they The local newspaper reports there is rumors of a petition circulating in a hamlet near Resident from Goderich and Seaforth appear to be generally pleased with the system.

Once the customers receive the containers and use them for three to four months, they appreciate the convenience of the new wheelie bins. The Association expanded its recycling program to include mixed rigid plastic containers starting in October and those with wheelie bins are very happy to have the capacity to manage the new materials. Others with a blue box are asking when they will receive their wheelie bin.

6.0 Lessons Learned

- Single stream processing technology can be applied to smaller material recovery facilities with competitive capital costs on a per tonne basis.
- $\omega \wp$ Single stream processing can generate quality materials for end markets.
- Optical machines can be very effective to assist in the separation of materials but have limitations like most sorting technologies.
- 4 Current disk separator technology can be used to recover smaller rural papers effectively.
- 5 Single stream fines can be effectively separated to meet end market requirements to recover glass, metals, and fibres. Plastic lids cannot be easily separated from broken glass without an optical machine.
- Automated collection is safer than manual collection
- \mathcal{C} Automated collection recovers more than manual collection.
- Residents prefer the use of the wheelie bins over the traditional blue box
- Plastic film can be recovered effectively in a single stream system.
- 10) Optical machines can be very effective to assist in the separation of materials but they must be maintained at regular intervals.
- 11) Today's technologies have the ability to be connected to the internet where diagnose quickly and efficiently to minimize downtime and repair costs. facilities with this level of technology should be remotely accessible. remote connections can be established by the equipment manufacturer's experts to
- 12) High speed conveyors such as those used to feed optical systems have a higher the belt, the higher the propensity. propensity for shaft failures because of their speed and belt tension. The wider
- 13) 100% Biodiesel is highly effective in reducing DPM emissions and improving air quality if other operating conditions are conducive to the use of the fuel.
- 14) A secondary optical pass used for plastic sorting improves the purity of the outgoing materials but not without loosing some system efficiency.
- 15) Drum feeders are an efficient tool to manage the system material flow but they introduce static electricity to some materials that needs to be managed